(2) The anè has not been raised to the height it was determined at the time of completing the project. Its level may therefore be raised by two or three feet.

Reply of Government.—Referred to the Chief Engineer for report.

SUBJECT No. 507.

Repairs to the breached anè across the Shimsha river near Chandanahalli.

Mr. J. Shama Iyengar, Kunigal Taluk.

Summary of discussion.—About thirty years ago, the ané across the Shimsha river near Chandanahalli breached and if it is repaired at a cost of Rs. 25,000, one thousand acres are available for wet cultivation. It is requested that it may be ordered to be repaired.

Reply of Government.—This will be unnecessary as the construction of the Markonhalli reservoir is under consideration.

SUBJECT No. 508.

A manegar for the tank at Kadaba.

Mr. K. Ramanujiengar, Gubb Taluk.

Summary of discussion.—A manegar for the tank at Kadaba is necessary.

Reply of Government.—Will be referred to Revenue Commissioner for consideration.

BANGALORE DISTRICT.

(Nos. 509—535.)

SUBJECT No. 509.

The broadening of the Bellandur Amanikere bund.

Mr. Veerappa Reddi of the Bangalore Taluk.

Summary of discussion.—The reduction of the width of the Bellandur Amanikere bund from 18 to 9 feet has been a great impediment to traffic in that quarter. In spite of repeated petitions, the old width has not been restored as yet. The same may be ordered to be done soon.

Reply of Government.—Referred to Deputy Commissioner for disposal in consultation with the Executive Engineer.

SUBJECT No. 510.

Aqueducts and the appointment of saudies for the Bellandur Amanikere Channels.

Mr. Veerappa Reddi, Bangalore Taluk.

Summary of discussion.—A revenue of about Rs. 5,000 is collected under the Bellandur Amanikere tank. There are two channels five miles long running from the tank. In the rainy seasons these always get choked by silt deposited from cross drainages tracts and the poor raiyats are often put to the necessity of paying tax without getting any supply of water. These crossings may be directed to be protected by acqueducts, the channels brought under channel rules, two saudies appointed to look after the distribution of water and the preservation of the channels in good order.

Reply of Government.—The question will be considered in the Public Works Department.

SUBJECT No. 511.

The repair of Krishnarajpura-Whitefield road by the Public Works Department.

Mr. Veerappa Reddi, Bangalore Taluk.

Summary of discussion.—The portion of the road from Krishnarajpur Railway Station to Whitefield of the Bangalore-Madras road has been ordered to be repaired by the Local Boards. Since this road is an important one and the Local Boards may not execute the work quite satis-